ATTACHMENT

5-SJM-SPB Document 48-21

ICONE Brand

Mineral Fiber Board

360





Dust hazard. Out and trim with knife, razor or hand saw. Do red cut with power equipment unless a clust collector is used on the equipment or local extracts is used and a NIOSH/MSHA-approved respirator is worn. Failure to follow these instructions may result in overexposure to althorne man-made mineral fiber. Althorne man-made mineral fiber and crystalline silica are thought to increase the risk of lung cancer. Overexposure to clust can cause eye, skin, nose, throat or respirator, Wear eye and skin protection.



Industrial Products
United States Gypetim Company
125 South Franklin Street
Chicago, IL. 60306

NW858-300/7-03 ©2003, United States Gypsum Company Printed and Produced in U.S.A. http://www.usg.com

FRAGILE-DO NOT DROP

RRST AID For skin intiation, rinso with cool water, followed by washing with soap and warm water. For eye inflation, fush eyes thoroughly with water for 15 minutes. If inflation persists, consult a physician. Product safety information: (800, 507-8899.)

THIS PRODUCT CONTAINS NO ASBESTOS

HANDLING Protect from impact and abresion to zvoid damage to all edges

INSTALLATINE Store and install at standard occupancy conditions (temperature 60° to 65° F) and relative huntidity (below 70% for at least 24 hours prior to installation). Extreme changes in temperature or frumidity may cause panels to expand, contract or warp.